


Turbocharger Bypass Valve

Base Part Number: 9K378

Removal

NOTE: Removal steps in this procedure may contain installation details.

1. Disconnect the electrical connector. Remove the bolts and the turbocharger bypass valve.
Torque: 53 lb.in (6 Nm)



Installation

1. To install, reverse the removal procedure.

Copyright © 2019 Ford Motor Company

